PES INC.

PRECISION ENVIRONMENTAL SERVICES, INC.

CONSULTING-ASSESSMENT-REMEDIATION
P.O. Box 149, Hadley, NY 12835
TEL. (518) 696-3151
FAX (518) 696-3152

	August 5, 1994
Mr. Chuck Schwer	1 (8)
State of Vermont Department of	ें डि
Environmental Conservation	
Hazardous Materials Management Division	* "
Sites Management Section	
103 South Main Street/West Office	E COMMISSION OF THE COMMISSION
Waterbury, Vermont 05671-0404	\$ 4

Re: Stewarts Ice Cream Co., Inc., shop #191, Main & Maple Streets, Poultney, Vermont Site #93-1531

Dear Mr. Schwer:

Enclosed for your review is one (1) copy of Precision Environmental Services, Inc.'s (PES's) Initial Site Investigation Report for the above referenced site. PES has recommended the installation of two additional monitoring wells and the implementation of interim remedial measures to reduce the contaminant volume on site. Once you have had an opportunity to review the information, please contact us at (518)696-3151 to discuss this site.

Sincerely,

PRECISION ENVIRONMENTAL SERVICES, Inc.

William A. Toran

Environmental Geologist

John J. Johnson

Geotechnical Director

enclosure

cc: C. Fowler - Stewarts

INITIAL SITE INVESTIGATION

STEWARTS ICE CREAM CO. INC., - SHOP #191 MAIN & MAPLE STREETS POULTNEY, VERMONT

Vt. - DEC Site #93-1531

PREPARED FOR: STEWARTS ICE CREAM COMPANY, INC. P.O. BOX 435 SARATOGA SPRINGS, NEW YORK 12866

(518)581-1201 CONTACT: CHAD FOWLER

PREPARED BY:

PRECISION ENVIRONMENTAL SERVICES, INC.
P.O. BOX 149
HADLEY, NEW YORK 12835
(518)696-3151
CONTACT: BILL TORAN

AUGUST, 1994

TABLE OF CONTENTS

1.0 INTRODUCTION
2.0 BACKGROUND1
2.1 Site Information
2.2 Site History1
2.3 Potential Receptor Survey2
3.0 SCOPE OF WORK
4.0 METHODOLOGIES AND RESULTS2
4.1 Monitoring Well Installation and Development2
4.2 Soil Sampling and Photoionization Analysis
4.3 Monitoring Well Gauging and Ground Water Gradient Determination
4.4 Monitoring Well Sampling and Ground Water Analysis
5.0 CONCLUSIONS5
6.0 RECOMMENDATIONS6
<u>FIGURES</u>
FIGURE 1 - Area Map
FIGURE 2 - Vicinity Map
FIGURE 3 - Site Map
FIGURE 4 - Ground Water Contour Map
FIGURE 5 - BTEX Distribution Map
TOOM 5 DILLE DISMOGRAM Map
TABLES
TABLE 1 - PID Soil Analysis Summary
TABLE 2 - Ground Water Analysis Summary

ATTACHMENTS

ATTACHMENT A - Neighboring Property List

ATTACHMENT B - Drilling Logs

ATTACHMENT C - Well Gauging Data Sheet

ATTACHMENT D - Laboratory Analysis Report

1.0 INTRODUCTION

Precision Environmental Services, Inc.(PES) was contracted by Stewarts Ice Cream Company, Inc. (Stewarts) to perform a limited subsurface investigation at Shop #191, located in Poultney, Vermont. An assessment of the soil and ground water characteristics and quality in the vicinity of former and present underground storage tanks (USTs) was performed to determine possible ground water contamination associated with the USTs.

2.0 BACKGROUND

2.1 Site Information

Stewarts Shop #191 is located at the southeast corner of Main and Maple Streets in the Village of Poultney, Rutland County, Vermont (Lat. 43°31'01",Long. 73°14'14"). The general site topography is flat with a very slight gradient to the west-northwest. The Poultney River borders the Village of Poultney to the south and west (approximately 1,700 and 2,600 feet, respectively, from the site). A tributary to the Poultney River is located approximately 900 feet southeast of the site. Refer to the Area Map (Figure 1).

The site is located in a mixed commercial and residential area. Main Street parallels the site's northern property border. Several commercial businesses are located on the north side of Main Street, directly across from the Stewarts Shop. Private residences are located west of the businesses on the north side of Main Street. The Poultney Public Library is located immediately adjacent to, and east of Stewarts. A public right of way (dirt alley/road) and a private residence exist south of Stewarts. Maple Street borders the Stewarts property to the West. Poultney Video and the Poultney Laundrette are located on the west side of Maple Street. Refer to the Vicinity Map for neighboring property locations (Figure 2). Property owners names and addresses (when available) are presented in Appendix A.

2.2 Site History

The site was purchased by Stewarts in 1983. According to Stewart's personnel, a three story brick structure measuring 153 feet by 43 feet occupied the site prior to Stewarts taking ownership.

The Stewarts property encompasses 0.37 acres. Stewarts Shop #191 presently occupies the site. The single story shop building is constructed of masonry block with a brick veneer and measures 47 feet by 45 feet. The building does not have a basement. Refer to the Site Map (Figure 3).

On November 8, 1993, four-4,000 gallon capacity single wall steel USTs were closed at the site. The closure was performed in response to one of the USTs failing a tightness test. Two pin size holes were observed in the bottom of UST #3. No apparent holes were observed in the remaining three USTs. Soil samples collected during UST closure indicated volatile organic compound (VOC) concentrations ranging from 1 part per million (ppm) to 340 ppm by photoionization detector (PID) analysis. Ground water

with a sheen was observed in the tank pit at a depth of approximately 13 to 14 feet below grade. Refer to the UST Closure and Site Assessment Form issued to the Vermont DEC on November 8, 1993. As a result of the UST closure, 530.51 tons of contaminated soil was transported and disposed of at Clean Berkshires, Inc.'s facility in Lanesboro, Massachusetts. The closed USTs were replaced with one-8,000 gallon capacity, and one split 8,000 gallon capacity double wall steel USTs. The new USTs were installed in the same excavation the closed USTs previously occupied.

2.3 Potential Receptor Survey

A survey to identify potential contaminant receptors was performed. Two municipal (Village of Poultney) water wells are located approximately 2,300 feet west of the site. The municipal water wells are located adjacent to the Poultney River, between the river and Green Mountain State College. The wells are used for supplying potable water to the Village of Poultney.

A survey of surrounding property owners indicated that all of the buildings in the area of interest have basements. However, generally the basement foundations do not have sumps and sump pumps due to the depth of ground water being greater than the basement floors. The average depth to the initial water table during monitoring well gauging on May 11, 1994 was 8.5 feet (refer to section 4.3).

Underground utilities (water and sewer lines) are located beneath Main and Maple Streets. These utilities are generally located at depths of less than 6 feet below grade (Figure 3).

3.0 SCOPE OF WORK

The purpose of this investigation was to assess the impact of petroleum contamination to ground water in the vicinity of the USTs. Tasks performed included:

- v Installation and development of 5 monitoring wells.
- ∇ Gauging of all monitoring wells and development of a ground water gradient map.
- v Ground water sampling and laboratory analysis of all monitoring wells.
- ∇ Preparation of a report of findings.

4.0 METHODOLOGIES AND RESULTS

4.1 Monitoring Well Installation and Development

On April 26, 1994, five 2- inch diameter PVC monitoring wells (MW-1, MW-2, MW-3, MW-4, and MW-5), were installed at the Stewarts site by Technical Drilling Services, Inc. under the supervision of a PES geologist. The wells were installed in overburden material using hollow stem auger drilling techniques.

Monitoring wells were installed to an average depth of is 17 feet below grade. The initial water table was encountered at depths ranging from 9 to 10 feet below grade at the time of drilling. The annular space surrounding the well screen was packed with clean silica sand to a depth of approximately 1.0 foot above the screened interval. Two foot bentonite seals were placed immediately above the sand pack. Each well was completed by cementing a steel, flush mounted protective manhole over the well riser. Refer to the enclosed drilling logs for construction details for individual wells (Attachment B).

The monitoring wells were installed around the spill location to aid in determining the impact of petroleum hydrocarbons on the surrounding subsurface. Monitoring well MW-1 was installed southeast and upgrading of the USTs. MW-2, MW-3 and MW-4 were installed down gradient and north, northwest, and west of the UST location, respectively. MW-5 was installed off site, in the Maple Street right of way, at a location further west of MW-3. The monitoring well locations are illustrated on Figure 3.

Well development was performed by repeatedly surging and bailing the monitoring wells to remove residual silt and clay. Approximately 5 volumes of ground water were purged from each monitoring well during bailing. Purged ground water was allowed to percolate into the ground in the vicinity of the monitoring wells.

4.2 Soil Sampling and Photoionization Analysis

Split spoon and auger cutting soil samples were obtained at each bore hole. The samples were described on drilling logs by a PES geologist using a modified Burmister classification system. The split spoon samples and drill cuttings were screened for volatile organic compounds (VOCs) during drilling operations using a photoionization detector (PID) calibrated to a benzene standard. Representative portions of split spoon and drill cutting samples obtained during the soil boring program were sealed in clean plastic bags and classified. After allowing for equilibration of the samples, the headspace in each sample was scanned with the PID by inserting the probe tip into the plastic bag. Soil sample descriptions and VOC concentrations are recorded on the respective drilling logs (Attachment B) and summarized in Table 1 below.

Table 1 - PID	Soil Ana	lysis Summary
---------------	----------	---------------

			MW I.D. a	and PID Rea	iding (ppm)
Depth (ft. below grade)	MW-1	MW-2	MW-3	MW-4	MW-5
5 - 7'	ND	ND	ND	ND	ND
7 -9'	ND	NA	NA	NA	NA
9 - 11'	ND	NA	NA.	NA	NA:
10 - 12'	NA	2	140	2	6
11 - 13'	ND	NA	NA	NA	NA
13 - 15'	ND	NA	. NA	NA	NA
15 - 17'	ND	1	25	1	17
17 - 19'	ND	NA	NA	NA	NA

ND = none detected

NA = not sampled

(different sampling interval)

The overburden material encountered in all of the boreholes generally consisted of sand with some gravel and minor quantities of silt. A silt layer was encountered at a depths of 18.5 and 17 feet below grade in borings MW-1, and MW-4, respectively.

VOCs were not detected during PID analysis of soil samples retrieved from boring MW-1. Soil samples retrieved from MW-2, 3, 4, and 5 indicated VOC concentrations ranging from none detectable to 140 parts per million (ppm) by PID analysis. Refer to the drilling logs (Attachment B)

4.3 Monitoring Well Gauging and Ground Water Gradient Determination

On April 26, 1994, the top of casings elevations for monitoring wells MW-1 through MW-5 were surveyed in order to calculate the ground water flow direction and gradient. The elevations were determined from a benchmark which was arbitrarily chosen as the top of the north end of the pump island lighting base. The benchmark was assigned an elevation of 100.00 feet. The elevations which resulted are accurate to +/_0.01 feet.

The depth to water in each monitoring well was gauged on May 11, 1994 using an electronic interface probe. Separate phase petroleum was not encountered in any of the monitoring wells at this time. From data collected, ground water flow on site was calculated to be in an west-southwesterly direction at an average gradient of 1.3%. This data is contained in Attachment C and is illustrated on the Ground Water Contour Map (Figure 4).

Depth to water ranges from 8.22 (MW-2) to 8.97 (MW-4) feet during the well gauging event. Ground water was observed at a depth of approximately 13 to 14 feet below grade during UST closure on November 8, 1993. This observed variation may be attributable to seasonal ground water fluctuations.

4.4 Monitoring Well Sampling and Ground Water Analysis

On May 11, 1994, monitoring wells MW-1, MW-2, MW-3, MW-4 and MW-5 were sampled for volatile organic compounds via EPA Method 602 modified to include methyl tertiary butyl ether (MTBE). Prior to sampling, a minimum of three well volumes of ground water was purged from the wells to provide collection of representative samples. Purged water was allowed to percolate into the ground in the vicinity of the respective wells. All samples were acidified and refrigerated for preservation, and delivered to Adirondack Environmental Services, Inc. in Albany, New York for analysis.

Laboratory results indicate total BTEX (benzene, toluene, ethylbenzene, and total xylenes) in monitoring wells MW-3, MW-4, and MW-5 at concentrations of 3,413 parts per billion (ppb), 4,305 ppb, and 7,150 ppb, respectively. The distribution of BTEX compounds in ground water is illustrated on Figure 5.

Methyl tertiary butyl ether (MTBE) was present in monitoring wells MW-1, MW-2, and MW-5 at concentrations of 2 ppb, 4 ppb, and 900 ppb, respectively. Laboratory reports are enclosed in Attachment D and summarized in Table 2 below.

Table 2 Ground Water Analysis Summary

	· · · · · · · · · · · · · · · · · · ·				
Well ID	BENZENE	TOLUENE	ETHYLBENZENE	XYLENES	MTBE
MW-1	< 0.5	< 1	<1	<1	2
MW-2	< 0.5	<1	<1	<1	4
MW-3	< 5	240	73	3100	<10
MW-4	< 5	2105	< 50	2200	<10
MW-5	440	410	300	6000	900

⁻ results expressed in ppb.

The contaminant plume illustrated in Figure 5 does not directly correspond to the ground water flow direction depicted in Figure 4. A slight variation of the flow direction may be attributed to the water table being relatively high during the spring season.

5.0 CONCLUSIONS

The following conclusions are offered, based solely on data collected from this limited subsurface investigation. Subsurface conditions at other locations on site may differ from those encountered during this investigation.

- ∇ Soil conditions generally consisted of sand with gravel and small quantities of silt. A silt layer was encountered at a depth of 18.5 feet below grade at boring MW-1.
- PID analysis of soil samples indicated no detectable concentrations of VOCs in boring MW -1. PID analysis of soil samples retrieved from borings MW-2-5 indicated VOC concentrations ranging from none detected to 140 ppm.
- Monitoring well gauging data indicates ground water flow is toward the west at an average gradient of 1.4%. The average depth to water on May 11, 1994 was 8.5 feet. Ground water was observed at a depth of approximately 13 to 14 feet below grade during UST closure on November 8, 1993. This indicates the water table is capable of fluctuating approximately 4 to 5 feet.
- v Laboratory results indicate total BTEX (benzene, toluene, ethylbenzene, and total xylenes) in monitoring wells MW-3, MW-4, and MW-5 at concentrations of 3,413 parts per billion (ppb), 4,305 ppb, and 7,150 ppb, respectively. Methyl tertiary butyl ether (MTBE) was present in monitoring wells MW-1, MW-2, and MW-5 at concentrations of 2 ppb, 4 ppb, and 900 ppb, respectively.

6.0 RECOMMENDATIONS


Based on the data collected during this limited investigation, PES recommends continued monitoring of the site. The monitoring wells should be sampled monthly to determine ground water contaminant concentration trends. Monitoring well sampling can be reduced to quarterly sampling and gauging once sufficient background data is established. Gauging data may be useful for determining the range of seasonal water table fluctuation, and its affect on the ground water flow/contaminant plume migration direction.


To further delineate the contaminant plume, two additional monitoring wells should be installed down gradient of the existing wells. One well should be installed on the west side of Maple Ave., south of MW-5. The second monitoring well should be installed on the south side of Main Street, west of MW-5.

Interim remedial measures should be taken in order to contain and reduce the volume of petroleum contamination in the subsurface. The site geology appears to be conducive to soil ventilation and/or air sparging remedial techniques. Soil ventilation may be used to initially remove a large percentage of the gasoline contamination. The soil ventilation system may be augmented by air sparging at a later date to remove residual contamination. PES recommends performing a soil ventilation pilot study to determine design parameters for this remedial technique. Details of the pilot testing can be presented in a Corrective Action Feasibility Pilot Test correspondence once corrective action is determined to be neccesary by the Sites Management Section of the DEC. The need for a ground water pump and treatment system to contain the contaminant plume will also be evaluated. The pump and treatment system may expedite site clean up by exposing contaminated soil below the water table.

This report was prepared in accordance with standards of environmental geologic practice generally accepted in Vermont at the time of this investigation. The investigation was conducted solely for the purpose of evaluating subsurface environmental conditions of the ground water with respect to the on-site petroleum release. No soil engineering or geotechnical references, conclusions, or recommendations are implied or should be inferred. Evaluation of the geologic and environmental conditions at the site for the purposes of this investigation are made from a limited number of observation points. Subsurface conditions may vary away from the data points available. In particular, the nature of the soil and ground water quality beyond the points sampled is unknown, and constituents of concern may be present that were not analyzed for during this investigation.


FIGURES







are approximate.

Map adapted from Village of Poultney tax maps. PRECISION ENVIRONMENTAL SERVICES, INC. Date: 7 - 1994 Project No.: Vicinity Map Scale: 1 Inch = 100 feet | Figure: 2 100' Drawn By: BT Location: Poultney, VT Stewarts Shop #191 Scale in Feet







ATTACHMENT A NEIGHBORING PROPERTY OWNERS

Neighboring Property Owners

Location

Property Owner

Preseau's Place (liquor store & deli)
 Main St.
 Poultney, VT. 05764

Edmond & Mary Preseau Rd 2, Box 197 Poultney, VT 05764

Debonis, Wright & Winpenny (attorneys)
 Main St.
 Poultney, VT 05764

same

Raymond Ellis Williams (insur. agent & home)
 19-23 Main St.
 Poultney, VT 05764

Raymond E. Williams PO Box 164 Poultney, VT 05764

4. James M. & Mary D. Foley (home) 17 Main St. Poultney, VT 05764 same

Lorraine & Robert P. Jones (home)
 Main St.
 Poultney, VT 05764

same

 BP Gas Station - MT. Associates Main St Poultney, VT 05764 MT. Associates 217 N. Main St. Rutland, VT 05701

Simple Styles (hair salon)
 Main St.
 Poultney, VT 05764

Mark W. & Beverly S. Fedolfi 5 Rae Terrace Poultney, VT 05764

8.&9. Tower Pizza & Poultney Launderette Corner of Main and Maple St.s Poultney, VT 05764 Lorraine & Robert Williams 24 College St. Poultney, VT 05764

Poultney Library
 Main St.
 Poultney, VT 05764

same

Ellen L. Jones
 Maple St.
 Poultney, Vt 05764

Ellen L. Jones 4642 S. 34th St. Arlington, VA. 22206

 Carmen H. Bissel Maple St. Poultney, Vt. 05764 Carmen H. Bissel 266 Private Rd. E. Patchague, NY

 Roxanne M. Cambell & Darryl West Maple St. Poultney, Vt. 05764 same

ATTACHMENT B DRILLING LOGS

	ECIS		TA	D. Box 149 Hadley, NY 12835 TEL: 518 696-8151 PAX: 518 696-8162 DRILLING LOG Page 1 of 1 DRILLING LOG
Project: Stewarts/Poultney,	VT CI	ient: Stewa	rts Ice Cre	Well/ Boring No. MW-1
Project No.:	Loc	cation: Main	& Maple	St.s, Poultney, Vt. Sketch Map:
Driller: Peter Dueshane	Log	ged by: <u>B.</u>	Toran	N ports
Drilling Contractor: TDS	Drilli	ing Method:	hollow st	1 1 · · · · · · · · · · · · · · · · · ·
Date Drilled: April 26,1994	Date	Developed:_	April 26,1	1994
M.P. Elev.: 99.16	W.L	Initial: <u> </u>	<u>0' </u>	V.L. Statie:
Total Depth of Hole: 19'		Diamete	er: <u>4.25"</u>	
Screen: Dia.: 2"	Length: 10'		Slot Size:	0.010 ^{it}
Casing: Dia.; 2"	Length: 7'		Туре:	PVC MAPLE STREET
Sand Pack: #1 I	Bentonite Seal:_	pellets	Protective	e Casing: <u>flush</u>
Depth Well (ft.) Construction	Notes (blows, etc.)	Sample Type/#	PID (ppm)	Description/ Soil Classification
0	roadbox	:		
	- cement	:		
	backfill riser	AF	ND	Brown, moist, med.(-) fine SAND.
	bentonite			
5	6-3-4-3	SS 5-7'	ND	do
	rec= 0.5'		MD	W
	5-5-4-9 rec= 0.75°	SS 7-9'	ND	do
- 10 -	5-3-4-4 rec= 0.25'	SS 9-11'	ND	Brown, wet, fine SAND, trace fine Gravel.
	5-7-6-7 rec≃ 1.5'	SS 11-13'	ND	Brown, wet,med.(+) fine SAND, trace fine Gravel.
	4-8-17-12 rec= 2.0'	SS 13-15'	ND	do
	9-22-13-13 rec= 1.0'	SS 15-17'	ND	Brown, wet, med.(-) fine SAND.
sand well	3-3-4-6 rec= 2.0'	SS 17-19'	ND	D. L. OTT OF PART CALL
pack screen	rec- 2.0			Brown, wet, SILT, little Silt.
20				EOE = 19'

Note: ND = no VOCs detected by PID analysis.

PES PRECI Environmental		TA	Box 149 Hadley, NY 12885 TEL: 518 696-3151 PAX: 518 696-3152 DRILLING LOG Page 1 of 1	
Project; Stewarts/Poultney, VT	Client: Stewa	rts Ice Cre	wam Co., Inc. Well/ Boring No. MW-5	2
Project No.:1	_ocation: Mair	& Maple	St.s, Poultney, Vt. Sketch Map:	
Driller: Peter Dueshane t	.ogged by: <u>B.</u>	Toran		_
Drilling Contractor: TDS D	rilling Method:	hollow at	em auger stewarts	
Date Drilled: April 26,1994 Da	te Developed:_	April 26,1	994	
M.P. Elev.: 98.86 V	/.L. Initial: 1	<u>.0' </u>	V.L. Static:	
Total Depth of Hole: 17'	Diamet	er: <u>4.25" :</u>	ID 93844	
Screen: Dia.: 2 ⁿ Length:	το,	Slot Size:	0.020"	
Casing: Dia.: 2 ⁿ Length:	7'	Type:	PVC MAPLE STREET	
Sand Pack: #2 Bentonite Sea	i:_pellets	_ Protective	Casing: flush	
Depth Well Notes (ft.) Construction (blows, etc.)	Sample .) Type/#	PID (ppm)	Description/ Soil Classification	
roadbox	., 13pcs #	(F)/		
0 cement			Asphalt	
backfill	AF	,,,,,	Brown, moist, SAND, some fine Gravel (fill).	
riser	A	ND		
bentonite 5				
9-4-5-6 rec= 1.2	SS 5-7'	ND	Brown-gray, moist, coarse(-)med. SAND, little med.(-)fine Grav	el.
	AF	1	·	
10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	· · · · · · · · · · · · · · · · · · ·			
2-2-3-4 rec= 1.5'	SS 10-12'	2	Brown, wet, med.(+)fine SAND, trace fine Gravel and Silt.	
	AF	1		
4-7-11-8	SS 15-17'	1	do.	
rec=2,0'				
sand well pack screen			EOE = 17'	
20				
		į		
		1		
			Note: ND = no VOCs detected by PID analysis.	

.

PRECI Environmental		P.O. Box 149 Hadley, NY 12885 TEL: 518 696-8151 PAX: 518 696-8152 DRILLING LOG Page 1 of 1
Project_ Stewarts/Poultney, VT	Client: Stewarts Ice	Cream Co., Inc. Well/ Boring No. MW-3
Project No.: L	ocation <u>: Main & Ma</u> j	le St.s, Poultney, Vt. Sketch Map:
Driller: Peter Dueshane t	ogged by: B. Toran	
Drilling Contractor: TDS D	rilling Method: <u>hollo</u>	
Date Drilled: April 26,1994 Da	te Developed; April :	
M.P. Elev.: 98.99' W	r.L. Initial; <u>10'</u>	_ W.L. Static:
Total Depth of Hole: 17'	Diameter: 4.2	
Screen: Dia.: 2" Length: 1	.0' Stot Si	ze <u>0.020*(12-17)/0.040*(12-7</u>)
Casing; Dia.: 2" Length: '	<u>" </u>	
Sand Pack: #2 Bentonite Sea	: pellets Protec	tive Casing: flush
Depth Well Notes (ft.) Construction (blows, etc	Sample PID Type/# (ppm	Describion Soil Cassilication
roadbox	1,750 " (1.1	,
cement		Brown, moist,fine SAND and SILT.
backfill	AF ND	Brown,moist,SAND, some fine Gravel.
riser		Diown, mouse, ozna, some and arava.
bentonite		
4-7-10-8 rec= 1.0'	SS 5-7' ND	Brown, moist, med.(+)fine SAND, little fine Gravel, trace Silt.
100-1.0		_
	AF 1	
10		
5-4-3-4 rec= 1.5'	SS 10-12' 140	Brown, wet, med.(+)fine SAND, little fine Gravel.
15 - 15	<u> </u>	
2-4-5-7 rec=2.0'	SS 15-17' 25	Brown, wet, fine SAND.
sand well		EOE= 17'
pack screen		302 1.
20 -		
		Note: ND = no VOCs detected by PID analysis.

	ECI		T.A.	DRILLING LOG Box 149 Hadley, NY 12885 Page 1 of 1
Project: Stewarts/ Poultney,	VT (lient: Stewa	rts Ice Cre	wam Co., Inc. Well/ Boring No. MW-4
Project No.:	Lo	ocation; Mair	a & Maple &	St.s, Poultney, Vt. Sketch Map:
Driller: Peter Dueshane	Lo	gged by:B.	Toran	XXX.5
Drilling Contractor: TDS	Dri	lling Method:	hollow st	tem auger
Date Orilled: April 26,1994	Date	Developed:	April 26,1	
M,P, Elev.; 98.651	w.	L. Initial; 1	<u>0'</u> v	V.L. Static:
Total Depth of Hole: 171	•	Diamet	er: <u>4.25"</u>	ID Oper
Screen: Dia.: 2"	Length: 10)'	Slot Size	0.020"(12-17)/0.040"(7-12)
Casing: Dia.: 2"	Length: 7'		Туре:	
Sand Pack: #2	Bentonite Seal:	pellets	_ Protective	Casing: flush
Depth Well (ft.) Construction	Notes (blows, etc.)	Sample Type/#	PID (ppm)	Description/ Soil Classification
	roadbox	1360 #	144)	
	cement		•	Asphalt Brown, moist, fine SAND and SILT, some fine Gravel
<u> </u>	backfill	AF	ND	Brown-gray, moist, medfine GRAVEL and SAND (difficult
$\parallel \parallel \parallel \parallel \parallel \parallel$	—riser		ND	drilling at 2.5')
5	bentonite			Duddow(f) wash from which
	22-6-5-7 rec= 1.5'	SS 5-7'	ND	Boulder(?) - rock fragments
	100-1.0			Brown, moist, med.(-)fine SAND, trace Silt.
		AF	1	
_ 10 X				
	6-4-5-6 rec= 2.0'	SS 10-12	2	Brown, wet, med.(+)coarse SAND, little fine Gravel.
		177		
		AF	1	
15	3-3-3-5	00.45.481	-	Brown, wet, med.(-)fine SAND, trace fine Gravel.
	rec=2.0'	SS 15-17'	1	Brown, wet, SILT.
sand well				
pack screen				EOE = 17'
20				
	ļ			
]			
				Note: ND = no VOCs detected by PID analysis.

	E C I S		LN	Box 149 Hadley, NY 12836 TRL: 518 696-3151 PAX: 518 696-3152 DRILLING LOG Page 1 of 1
Project Stewarts/Poultney,	VT Clie	ent: Stewar	ts Ice Cres	well/ Boring No. MW-5
Project No.:	Loca	ation; Main	& Maple S	Sketch Map:
Oriller: Peter Dueshane	Logg	ged by: <u>B. '</u>	Toran	
Drilling Contractor: TDS	Drilli	ng Method:_	hollow ste	em auger
Date Drilled: April 26,1994	Date D	Developed:	April 26,19	994
M.P. Elev.: 98.041	W.L.	Initial: 9'	w	<u> </u>
Total Depth of Hole: 17'				30%
Screen: Dia.: 2" L				0.020"
Casing: Dia.: 2" L	ength: 7'		Type: <u>1</u>	PVC MAPLE STREET
Sand Pack: #2 B			- t	Casing: <u>flush</u>
Depth Well (ft.) Construction	Notes blows, etc.)	Sample Type/#	PID (ppm)	Description/ Soil Classification
0	roadbox			Asphelt
	cement		-	ASTRACT
-	backfill	AF	ND	Brown, moist, fine GRAVEL and SAND.
	niser 			
- 5	-			
	7-7-5-7 rec= 1.0'	SS 5-7'	ND	Brown, moist, SAND, some med.(-)fine Gravel.
		AF		
10 -	1-2-4-4 rec= 1.0'	SS 10-12'	6	Brown, wet, med.(+)fine SAND, trace Gravel.
		АF		
- 15 - S	101014			
	1-3-10-14 rec=1.5'	SS 15-17'	17	Brown, wet, coarse(+)fine SAND, trace fine Gravel.
sand well pack screen				
20				
 				
				Note: ND = no VOCs detected by PID analysis.

ATTACHMENT C WELL GAUGING DATA SHEET

WELL GAUGING DATA SHEET

SITE NAME: Stewarts Shop #191, Poultney, Vt.

LOCATION: Main & Maple St.s, Poultney, Vt.

WEATHER: clear, 70 degrees F

DATE: May 11, 1994

TECHNICIAN: J. Johnson

INSTRUMENT ID: I.P. (ORS) # 347

TECHNICIA						INT ID. I.F. (ORS) # 347
WELL NO.	T.O.C.	D.T.P.	D.T.W.	PROD. LAYER	WATER TABLE	OBSERVATIONS:
3 1000 P			5 5 5		ELEV.	
MW-1	99.16	NA	8.31	0.00	90.85	
MW-2	98.86	NA	8.22	0.00	90.64	
MW-3	98.99	NA	8.71	0.00	90.28	slight petro, odor
MW-4	98.65	NA	8.97	0.00	89.68	very slight petro odor
MW-5	98.04	NA	8.43	0.00	89.61	slight petro. odor

PRODUCT REMOVED FROM WELLS NO XXXX

VES

SHEEN CONFIRMED BY BAILOR?

NO

YES XXXX

WELLS SAMPLED?

NO

YES XXXX

ATTACHMENT D LABORATORY ANALYSIS REPORT



LABORATORY REPORT

for

Stewarts Ice Cream Company PO Box 435 Saratoga Spring, NY 12866

Attention: Chad Fowler

Report date: 05/25/94

Number of samples analyzed:

AES Project ID: 940512AS

Invoice #: 137763

CC: M. Passaretti Precision Enviro

ELAP ID#: 10709 AIHA ID#: 12144-001

Page

5



CLIENT: Stewarts Ice Cream Company

Date Sampled:

05/11/94

CLIENT'S SAMPLE ID: MW-1

Date sample received: 05/12/94

AES sample #: 940512AS01

Samples taken by: John Johnson

Location: Poultney, VT

MATRIX: water grab

			3-1	<i>.</i>	
PARAMETER PERFORMED	METHOD	RESU	ULT UNITS	NOTEBK REF	TEST DATE
Benzene	EPA-602	<0.5	5 ug/l	PB-C	05/19/94
Toluene	EPA-602	<1	ug/l	PB-C	05/19/94
Ethylbenzene	EPA-602	<1	ug/l	PB-C	05/19/94
Chlorobenzene	EPA-602	<1	ug/l	PB-C	05/19/94
p-Dichlorobenzene	EPA-602	<1	ug/l	PB-C	05/19/94
m-Dichlorobenzene	EPA-602	<1	ug/l	PB-C	05/19/94
o-Dichlorobenzene	EPA-602	<1	ug/l	PB-C	05/19/94
Xylenes	EPA-602	<1	ug/l	PB-C	05/19/94
Methyl-t-Butyl Ether	EPA-602	2	ug/l	PB-C	05/19/94



CLIENT: Stewarts Ice Cream Company

Date Sampled:

05/11/94

CLIENT'S SAMPLE ID: MW-2

Date sample received: 05/12/94

AES sample #: 940512AS02

Samples taken by: John Johnson

Location: Poultney, VT

MATRIX: water grab

			-		
PARAMETER PERFORMED	METHOD	RESULT	UNITS	NOTEBK REF	TEST DATE
Benzene	EPA-602	<0.5	ug/1	PB-C	05/19/94
Toluene	EPA-602	<1	ug/l	PB-C	05/19/94
Ethylbenzene	EPA-602	<1	ug/l	PB-C	05/19/94
Chlorobenzene	EPA-602	<1	ug/l	PB-C	05/19/94
p-Dichlorobenzene	EPA-602	<1	ug/l	₽B-C	05/19/94
m-Dichlorobenzene	EPA-602	<1	ug/l	РВ-С	05/19/94
o-Dichlorobenzene	EPA-602	<1	ug/l	PB-C	05/19/94
Xylenes	EPA-602	<1	ug/l	PB-C	05/19/94
Methyl-t-Butyl Ether	EPA-602	4	ug/l	PB-C	05/19/94



CLIENT: Stewarts Ice Cream Company

Date Sampled:

05/11/94

CLIENT'S SAMPLE ID: MW-3

Date sample received: 05/12/94

AES sample #: 940512AS03

Samples taken by: John Johnson

Location: Poultney, VT

MATRIX:

	warkix: Macer		grat)	
PARAMETER PERFORMED	METHOD	RESULT	UNITS	NOTEBK REF	TEST DATE
Benzene	EPA-602	<5	ug/l	PB-C	05/19/94
Toluene	EPA-602	240	ug/l	PB-C	05/19/94
Ethylbenzene	EPA-602	73	ug/l	PB-C	05/19/94
Chlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
p-Dichlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
m-Dichlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
o-Dichlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
Xylenes	EPA-602	3100	ug/l	PB-C	05/19/94
Methyl-t-Butyl Ether	EPA-602	<10	ug/l	PB-C	05/19/94



CLIENT: Stewarts Ice Cream Company

Date Sampled:

05/11/94

CLIENT'S SAMPLE ID: MW-4

Date sample received: 05/12/94

AES sample #: 940512AS04

Samples taken by: John Johnson

Location: Poultney, VT

MATRIX: water

	INTIVIANT WELCH		dra	ט	
PARAMETER PERFORMED	METHOD	RESULT	UNITS	NOTEEK REF	TEST DATE
Benzene	EPA-602	<5	ug/l	PB-C	05/19/94
Toluene	EPA-602	2105	ug/l	PB-C	05/19/94
Ethylbenzene	EPA-602	<50	ug/l	PB-C	05/19/94
Chlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
p-Dichlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
m-Dichlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
o-Dichlorobenzene	EPA-602	<50	ug/l	PB-C	05/19/94
Xylenes	EPA-602	2200	ug/l	PB-C	05/19/94
Methyl-t-Butyl Ether	EPA-602	<10	ug/l	PB-C	05/19/94



CLIENT: Stewarts Ice Cream Company

Date Sampled:

05/11/94

CLIENT'S SAMPLE ID: MW-5

Date sample received: 05/12/94

AES sample #: 940512AS05

Samples taken by: John Johnson

Location: Poultney, VT

ATRIX:	water
--------	-------

	,	174001		grab		
PARAMETER PERFORMED	METHO	<u>ac</u>	RESULT	UNITS	NOTEBK REF	TEST DATE
Benzene	EPA-60)2	440	ug/l	PB-C	05/19/94
Toluene	EPA-60)2	410	ug/l	PB-C	05/19/94
Ethylbenzene	EPA-60)2	300	ug/l	₽B-C	05/19/94
Chlorobenzene	EPA-60)2	<100	ug/l	PB-C	05/19/94
p-Dichlorobenzene	EPA-60)2	<100	ug/l	PB-C	05/19/94
m-Dichlorobenzene	EPA-60)2	<100	ug/l	PB-C	05/19/94
o-Dichlorobenzene	EPA-60	02	<100	ug/l	PB-C	05/19/94
Xylenes	EPA-60	02	6000	ug/l	PB-C	05/19/94
Methyl-t-Butyl Ether	EPA-60)2	900	ug/l	PB-C	05/19/94

APPROVED BY:

Report date: 05/25/94

6

Taxa Danis



314 North Pearl Street Albany, New York 12207 518-434-4546/434-0891 FAX

A full service analytical research laboratory offering solutions to environmental concerns

CHAIN OF CUSTODY RECORD

CLIENT HAME PESS S ICC CICA ADDRESS / DICK 143,1	Theort's m Co Huller Ny 12835	PROJECT NAME (Low Portiney, 1 Shup = 19	estion) J+.		SAMPLERS: (Names) By Juhn Juhn Juhn (SAMPLERS: (Signature)				i	
Tax-tag		Direct Bill	١			35: (S ~_/_	_	۴	<u>~</u>	
aes Sample number	SAMPLE IDENTIF	LIENT ICATION & LOCATION		FED	TIME Awa.m. Pwp.m.	S.		TYPE	NUMBER OF CONT'S	ANALYSIS REQUIRED
1 <u>4047 F1001</u> 1	MW·	/	5/11/9	У	1	1/2	(၁	X	2	EPA (02 +MTBE
<u></u> (Q)	'MW - 6	?			,	н.		X	2	
어	MW 3	}			\ <u>\</u>	-1 1		X	2	
<u>04</u>	MW- 4 MW- 5	,			<u> </u>	⊣ !		X	J	
65	MW- 5				٦ =	- i. 1		χ	7	\bigvee
			•		* J *					
					<u> </u>	-				
					4	┥ .				
					4	4				
	·				A	→				
					4	-				
				-	4	-				
					A	-+				
Turnaround Time:	normal				Labor	ato	ry A	ppro	vai:	
Relinquished by:			Received b	y: (s/	gnature)			<u></u>		Syl Date/Time
Relinquished by: (Signature)			Received by: (Signature)					Date/Time		
Relinquished by: (signature)			Received by: (Signature) Date/Time					Date/Time		
Dispatched by: (5/o	nature)	Date/	Time F	teçei	ived for	r La	bor	tory	by	Date/Time 5 / 7:54 V.30
Method of Shipme	_	S	nd Report		Sul To	0	_(` ^-			Client Phone No.: 696-315/

The Laboratory reserves the right to return hazardous samples to the client or may levy an appropriate fee per container for disposal.